SAFETY RECALL

TO REPAIR ALL DROP-SIDE CRIBS

The drop side hardware of the cribs below can fail, causing the drop side to detach from the crib. When the drop side detaches it creates a space in which an infant or toddler can become entrapped and suffocate or strangle.

AFFECTED MODELS

EXPOSED HARDWARE

371 Jenny Lind
391 Jenny Lind
591 Alpha
2991 Sleigh
4091 Lauren
4191 Alexandria
1701 Caleb
2301 Twinkle
4001 Lauren
4491 Lauren
4291 Naomi
5201 Bailey
5691 Lauren
2191 Oxford
3991 Pine

HIDDEN HARDWARE

4801 Anastasia
3101 Leonardo
3401 Michelangelo
5901 Annabelle
5921 Roxanne/Kendall
5941 Annabelle/Kristen
W5941 Roxanne
6001 Robin

Immediately stop using these drop-side cribs and contact Million Dollar Baby to receive free repair kit at:

(888) 673-6488 or visit www.themdbfamily.com/safety

In Cooperation with the U.S. Consumer Product Safety Commission

POST UNTIL October 28th, 2010